

PRIDE OF PLACE 2020Facility # 126Name: Agnes Hodge

Priority	Component Description	Component Deficiency	Estimate
2	Line painting- parking lot and school yard	Faded Lines	\$ 2,500.00

Facility # 157Name: Banbury Heights

Priority	Component Description	Component Deficiency	Estimate
1	Security Cameras	Old, insufficient number of cameras	\$ 20,000.00

Facility # 101Name: Bellview

Priority	Component Description	Component Deficiency	Estimate
1	Renewal of gym floors and walls	Parquet floor is in need of sanding, new lines, paint walls	\$ 20,000.00

Facility # 512Name: Bloomsburg

Priority	Component Description	Component Deficiency	Estimate
1	Clean and treat stage drapes	Drapes did not pass latest testing	\$ 1,500.00
2	New blinds in rooms 02 , 04 and 36	Offices require blinds for lockdown	\$ 2,500.00
4	Repaint gym and stage walls- room 23	School was repainted- gym needs to match	\$ 10,000.00

Facility # 513Name: Boston

Priority	Component Description	Component Deficiency	Estimate
1	Upgrade remaining door knobs to BEST®	For lockdown purposes	\$ 5,000.00
2	3 additional outlets in each upstairs classrooms	Health and safety; currently not enough receptacles	\$ 5,000.00

Facility # 156Name: Branlyn

Priority	Component Description	Component Deficiency	Estimate
1	Paving Kindergarten Enclosure	Very uneven and covered in wood chips	\$ 10,000.00

Facility # 106Name: Brier Park

Priority	Component Description	Component Deficiency	Estimate
1	Replace front foyer floor	Update old and worn flooring	\$ 15,000.00

Facility # 104Name: Burford

Priority	Component Description	Component Deficiency	Estimate
1	New P.A System	Old, worn and not working in all classrooms	\$ 10,000.00

Facility # 713Name: Caledonia Centennial PS

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	Does not exist	\$ 20,000.00

Facility # 108Name: Cedarland

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	Current system not working	\$ 10,000.00
2	Window Covering- Various Rooms	Existing are old and not working properly	\$ 10,000.00

Facility # 109Name: Centennial Grand Woodlands

Priority	Component Description	Component Deficiency	Estimate
1	Painting Classroom Walls/ Staff Room	Requires updating	\$ 10,000.00

Facility # 110

Name: Central Brantford

Priority	Component Description	Component Deficiency	Estimate
1	Paint classrooms	Old paint in classrooms - paint as many as possible	\$ 10,000.00

Facility # 161

Name: Cobblestone

Priority	Component Description	Component Deficiency	Estimate
1	Update Student Washrooms	Paint on walls is chipped, partitions require replacement	\$ 10,000.00

Facility # 539

Name: Courtland

Priority	Component Description	Component Deficiency	Estimate
1	Extend chain link fence along K/G area at road	Need to extend this fence to ensure student safety	\$ 5,000.00
2	Painting of classroom walls, ebase 25,26,22,28,29,21,20	Walls peeling	\$ 5,000.00

Facility # 543

Name: Delhi Public

Priority	Component Description	Component Deficiency	Estimate
1	Outside wall southside of school	Ceiling trusses , window panels and wall needs painting	\$ 10,000.00

Facility # 114

Name: Dufferin

Priority	Component Description	Component Deficiency	Estimate
1	Painting- Lower Washrooms/ stage walls/ Stairwells	Requires updating	\$ 10,000.00

Facility # 115

Name: Echo Place

Priority	Component Description	Component Deficiency	Estimate
1	VAT and carpet replacement (05,12,22,31,32,34)	Old and worn floor	\$ 10,000.00
3	New blinds classrooms	Old and worn	\$ 5,000.00

Facility # 164Name: Ecole Confederation

Priority	Component Description	Component Deficiency	Estimate
1	Kitchen Expansion	Small expansion of current area is required	\$ 20,000.00

Facility # 521Name: Elgin Ave.

Priority	Component Description	Component Deficiency	Estimate
	No Submission	New blinds to replace current ones	\$ 5,000.00

Facility # 103Name: GELA Rawdon

Priority	Component Description	Component Deficiency	Estimate
2	Gym kitchen	Needs renovating	\$ 10,000.00

Facility # 119Name: Glen Morris

Priority	Component Description	Component Deficiency	Estimate
1	Kitchen Expansion	Small expansion of current area is required	\$ 10,000.00

Facility # 120Name: Graham Bell

Priority	Component Description	Component Deficiency	Estimate
2	Window Coverings	Replace old, broken or missing blinds	\$ 10,000.00

Facility # 121Name: Grandview

Priority	Component Description	Component Deficiency	Estimate
1	Window Covering	Replace old, broken or missing blinds	\$ 10,000.00

Facility # 123

Name: Greenbrier

Priority	Component Description	Component Deficiency	Estimate
	No Submission	Painting of interior walls	\$ 5,000.00

Facility # 722

Name: HAGERSVILLE ES

Priority	Component Description	Component Deficiency	Estimate
1	Painting rooms 107,108,131,139,148, 149	Paint needs updating	\$ 10,000.00

Facility # 538

Name: Houghton

Priority	Component Description	Component Deficiency	Estimate
1	New flooring in Port-pack, rooms 64, 65, 66	Floor tiles peeling and worn, possible floor damage	\$ 10,000.00

Facility # 125

Name: James Hillier

Priority	Component Description	Component Deficiency	Estimate
1	Painting	Radiator covers, doors & frames and trim through out school	\$ 10,000.00

Facility # 718

Name: Jarvis

Priority	Component Description	Component Deficiency	Estimate
1	Blinds in rooms 18,19,20,21,22,23,24,25 and 26	Old, worn or don't exist	\$ 10,000.00
3	WR's 11 & 12	Needs renovating	\$ 10,000.00

Facility # 719

Name: JL Mitchener

Priority	Component Description	Component Deficiency	Estimate
2	Renovate WR's (1021,1022,1048,1050,1053,1054,1059,1060,1061,1063A)	Need upgrading	\$ 15,000.00

Facility # 129

Name: King George

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	Doesn't exist	\$ 20,000.00

Facility # 542

Name: Lakewood

Priority	Component Description	Component Deficiency	Estimate
1	Roller blinds on remaining classroom windows south side	Reduce sun light and lock down	\$ 5,000.00
2	Replace Bradleys in girls washrooms- 2010, 1059	Original Bradley sinks	\$ 7,500.00

Facility # 534

Name: Langton Public

Priority	Component Description	Component Deficiency	Estimate
1	Renovate Kindergarten washroom- ebase 48	Paint/repair walls, new floors, vanity and plumbing fixtures,	\$ 7,500.00
2	Repair/Replace flooring	two areas of floor need repair/replacement	\$ 5,000.00

Facility # 130

Name: Lansdowne

Priority	Component Description	Component Deficiency	Estimate
1	Replace soccer nets	Replace 4 old post with new ones	\$ 6,000.00

Facility # 527

Name: Lynndale Hts.

Priority	Component Description	Component Deficiency	Estimate
1	Retaining Barrier in the kindergarten yard between the pavement and the field	Erosion occurring in the yard, dirt washing onto the pavement causing a safety hazard	\$ 10,000.00
5	New games painted on asphalt	Parking addition removed some, others faded	\$ 1,500.00

Facility # 132

Name:

Major Ballachey

Priority	Component Description	Component Deficiency	Estimate
1	Asphalt for accessible parking	Required for AODA	\$ 7,500.00
2	Flooring (102,103)	Old residential vinyl floor needs replacing	\$ 12,000.00

Facility # 728

Name:

Mapleview

Priority	Component Description	Component Deficiency	Estimate
----------	-----------------------	----------------------	----------

Facility # 134

Name:

Mt. Pleasant

Priority	Component Description	Component Deficiency	Estimate
1	Bathroom Renovation	Replace fixtures, plumbing and paint	\$ 10,000.00

Facility # 136

Name:

North Ward

Priority	Component Description	Component Deficiency	Estimate
1	Window Covering	Falling apart and do not operate correctly	\$ 10,000.00

Facility # 148

Name:

Oakland - Scotland

Priority	Component Description	Component Deficiency	Estimate
1	Painting of doors and frames in J-I wing to match front and primary hall, ebase 28,31,33,34	Chipped, peeling paint	\$ 5,000.00
3	Replace ceiling tiles in hallways throughout building, 18,18A,09,02,01,28,31,33,34	Tiles are stained and cracked	\$ 5,000.00

Facility # 721

Name:

Oneida Central

Priority	Component Description	Component Deficiency	Estimate
1	Flooring replacement in rooms 02,04,27 and 27A	Old VAT floors	\$ 7,000.00

Facility # 139

Name: Onondaga Brant

Priority	Component Description	Component Deficiency	Estimate
1	All exterior doors replaced (01,03,08)	Old and worn out	\$ 10,000.00

Facility # 140

Name: Paris Central

Priority	Component Description	Component Deficiency	Estimate
1	Replace Floor	Remove carpet from hallways	\$ 10,000.00

Facility # 537

Name: Port Rowan

Priority	Component Description	Component Deficiency	Estimate
1	Replace window coverings in ebase 46, 47, 48 and 49	Tattered, worn	\$ 3,000.00
2	Paint trim and interior doors	Throughout school where needed, paint peeling off	\$ 10,000.00

Facility # 142

Name: Prince Charles

Priority	Component Description	Component Deficiency	Estimate
2	Painting Hallways	Paint peeling and needs updating	\$ 10,000.00

Facility # 143

Name: Princess Elizabeth

Priority	Component Description	Component Deficiency	Estimate
1	Fence for kindergarten area at front of school	Current safety risks with kinders leaving school property	\$ 7,000.00
2	Continue to replace curtains with roller blinds	Any/all of 34,32,19,18,58,57,07,31,47 in order of preference	\$ 5,000.00

Facility # 723

Name: Rainham

Priority	Component Description	Component Deficiency	Estimate
1	Jr playground swings - pea gravel surfacing	Pea gravel has turned into mulch	\$ 10,000.00
4	Replace cabinets/countertop/sink in 2 classrooms	Old and worn	\$ 7,000.00

Facility # 733Name: River Heights

Priority	Component Description	Component Deficiency	Estimate
1	Blinds for 1st floor classrooms (116-184)	Old and worn	\$ 10,000.00
2	Paint for intermediate corridor & rooms (117-190)	Old paint	\$ 10,000.00

Facility # 146Name: Russell Reid

Priority	Component Description	Component Deficiency	Estimate
2	Coat Hooks and Shelves	Lockers have no doors, remove and install hooks and shelves	\$ 10,000.00

Facility # 160Name: Ryerson Heights

Priority	Component Description	Component Deficiency	Estimate
1	Kinderpen project	Address kinder pen surface issues, drainage, mud, etc.	\$ 10,000.00

Facility # 724Name: Seneca Central

Priority	Component Description	Component Deficiency	Estimate
1	Replace blackboards with whiteboards	Chalk boards are old and dust collectors. Need to update.	\$ 10,000.00
2	Replace all curtains with blinds	Current curtains are old and worn	\$ 5,000.00

Facility # 150Name: St. George - German

Priority	Component Description	Component Deficiency	Estimate
1	Window Coverings	Some are damaged or missing	\$ 10,000.00
2	Painting	Chipping and Peeling	\$ 10,000.00

Facility # 519Name: Teeterville

Priority	Component Description	Component Deficiency	Estimate
1	Painting heat registers in every classroom	Registers are starting to chip and fade	\$ 10,000.00
3	Painting cupboards throughout school	For added protection against possible mould growth	Budget

Facility # 715Name: Thompson Creek

Priority	Component Description	Component Deficiency	Estimate
1	Replacement/addition of window blinds	Safety issue for lockdown	\$ 10,000.00

Facility # 726Name: Walpole North

Priority	Component Description	Component Deficiency	Estimate
1	Painting of classrooms 05,06,07,10 and 19	Old paint	\$ 10,000.00
2	Install new soffit at entrance	Had been removed, now birds/insects are nesting in space.	\$ 5,000.00

Facility # 529Name: Walsh

Priority	Component Description	Component Deficiency	Estimate
1	Celling fans in ebase rooms 31,33,72,75 and 76	Continuation of fan installation to the rest of the classes	\$ 3,000.00
3	Roller blinds, 03,04,05,08,09,10,11,22,23,31,33,49,50,53,54,57,58,75	Continue of roller blind installation	\$ 5,000.00

Facility # 162Name: Walter Gretzky

Priority	Component Description	Component Deficiency	Estimate
	No Submission	Painting of walls	\$ 5,000.00

Facility # 516Name: Waterford Public

Priority	Component Description	Component Deficiency	Estimate
2	Lockable storage cabinets built on the side of the gym stage and along the walls of one change room	Place to store gym equipment and to ensure it is in locked cabinets as we have many rentals. Our gym equipment room was not expanded when our school doubled in size and there is not enough room to store all of our equipment.	\$ 5,000.00

Facility # 524

Name: West Lynn

Priority	Component Description	Component Deficiency	Estimate
1	Painting of classroom wall	old paint needs a new coat	\$ 5,000.00

Facility # 154

Name: Woodman

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	Only had a rudimentary DVR and analog cameras	\$ 15,000.00

Facility # 271

Name: Brantford Collegiate Institute

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	System dated and not operating correctly	\$ 15,000.00
3	Painting Double Gym	Walls and ceiling need painting	\$ 20,000.00

Facility # 729

Name: Cayuga SS

Priority	Component Description	Component Deficiency	Estimate
3	Outdoor Special Education area	No fence currently	\$ 3,500.00

Facility # 505

Name: Delhi DSS

Priority	Component Description	Component Deficiency	Estimate
1	Installation of roller blinds in staff room E base1051	No window covers are currently installed. Safety and privacy issue during lock down as windows face onto back playing field.	\$ 4,000.00
3	Re-tread stairs at exits 3,4,5, ebase 2017, 2023, 2038	Treads and capping has become worn and slippery, concerns that student, staff and guest safety is at risk	\$ 15,000.00

Facility # 730

Name: Dunnville SS

Priority	Component Description	Component Deficiency	Estimate
1	Floor Tiles in room 3005, 3008, etc	Tiles are worn and lifting due to age	\$ 15,000.00
2	Painting (1035,1127,2025,2028,2056)	Peeling paint, cracks need filling	\$ 10,000.00

Facility # 731

Name: Hagersville SS

Priority	Component Description	Component Deficiency	Estimate
1	Water/sink/handwashing in staffroom and improve accessibility (2025)	No water, not fully accessible	\$ 10,000.00
2	Replace floors (2009,2010,2011)	Old and worn	\$ 15,000.00

Facility # 732

Name: McKinnon Park SS

Priority	Component Description	Component Deficiency	Estimate
1	Replace carpet with LVT in rooms 1034,1022,1023,1024,1143,1144 and 1017	Old and worn	\$ 20,000.00

Facility # 274

Name: North Park CVS

Priority	Component Description	Component Deficiency	Estimate
1	Upgrade Family studies Kitchen	Existing is in poor shape, handles falling off, water damaged	\$ 10,000.00
2	Locker/ Locker Door Replacement	Damaged, broken doors, Paint chipping	\$ 10,000.00

Facility # 275

Name: Paris DHS

Priority	Component Description	Component Deficiency	Estimate
1	Painting Halls, Doors, Stairwells, Railings	Continue Process of painting these areas	\$ 10,000.00
2	Replace Kitchen cupboards, countertops in Foods Lab	Area is showing its age (35 years)	\$ 10,000.00

D-1-aFacility # 276

Name:

Pauline Johnson CVS

Priority	Component Description	Component Deficiency	Estimate
1	Replace as many lockers as possible (1st floor)	lockers are old and in poor condition	\$ 10,000.00
2	Pulse hallway display cabinets	Area where lockers were removed was never finished	\$ 5,000.00
3	Replace hallway ceiling tiles	ceiling tiles old and not in good condition	\$ 20,000.00

Facility # 501

Name:

Simcoe CS

Priority	Component Description	Component Deficiency	Estimate
1	Painting of all classroom doors and hallway walls	Current paint is peeling	\$ 10,000.00
2	Gym and drama room drapes	Do not meet fire code	\$ 10,000.00

Facility # 273

Name:

Tollgate TSC

Priority	Component Description	Component Deficiency	Estimate
1	Security Camera System	System dated and not operating correctly	\$ 25,000.00

Facility # 509

Name:

Valley Heights SS

Priority	Component Description	Component Deficiency	Estimate
1	Window Coverings in guidance office(1012), cws office (1071), 2 portables at Houghton, 1076 and 2014	These areas lack window covering for lock down	\$ 2,500.00
3	Sidewalk repair/replacement by greenhouse	The sidewalks in this area are in need of repair	\$ 10,000.00

Facility # 507

Name: Waterford DHS

Priority	Component Description	Component Deficiency	Estimate
1	Upgrades to main camera system and the addition of 4 cameras	Outside cameras need to be added and continue the upstairs, main system is glitches and needs improvements	\$ 25,000.00
3	Paint and wall repair in room ebase #1015 and 1070	Paint needs updated and repairs to drywall	\$ 15,000.00
5	Ceiling fans on second floor	Need air movement	\$ 5,000.00

Total \$995,500.00

Please note that each of these projects will be completed to the approved estimated value.